

FIG 1





FIG 2




FIG 3

4/7




FIG 4

Assessment of the image 31:

Very good, good, moderate, poor

Comment

80

FIG 8

The image was recorded with a

Magnetic resonance appliance

Computer tomograph

Lithotripter

Ultrasound appliance

X-ray appliance

51

50

FIG 5

The image was recorded with a magnetic resonance appliance in the course of a

Head examination

Lung examination

Heart examination

60

FIG 6

Ranking list of images recorded with a magnetic resonance appliance, which have been provided by

university A on January 26, 2001,

university B on January 3, 2001,

hospital A on January 5, 2001,

university C on December 22, 2000,

university A on December 20, 2001,

university D on January 24, 2001,

hospital B on January 24, 2001

70

FIG 7